

COMPATIBLE DIMMER

4-inch Slim Multi— DR40RSM

| Lutron® | | | Cooper® | | | Leviton® | | |
|--------------|---------------|-------------------|--------------|---------------|-------------------|--------------|---------------|-------------------|
| Model Number | Dimming Range | Max # of Fixtures | Model Number | Dimming Range | Max # of Fixtures | Model Number | Dimming Range | Max # of Fixtures |
| DVCL-153P | 5%-100% | 10 | 9531AW | 5%-100% | 12 | IPL06 | 5%-100% | 10 |
| DVCL-253P | 5%-100% | 20 | DAL06P | 10%-100% | 12 | 6672 | 5%-100% | 4 |
| MACL-153M | 5%-100% | 10 | SLC03P | 10%-100% | 12 | DSM0-1LZ | 5%-100% | 36 |
| LGCL-153P | 5%-100% | 10 | SAL06P | 15%-100% | 12 | - | - | - |
| AYCL-253P | 5%-100% | 20 | - | - | - | - | - | - |
| CTCL-153P | 10%-100% | 10 | - | - | - | - | - | - |
| SELV-300P | 10%-100% | 25 | - | - | - | - | - | - |
| TGCL-153P | 15%-100% | 10 | - | - | - | - | - | - |

Note:

- * All model above have been officially tested by the factory.
- * A report of using another dimmers which are not on the list is welcome to present to us.
- * There is no guarantee or warranty on every installation with all dimmers on the list as your result might vary under uncertain causes.
- * Some dimmers require trim adjustment to eliminate flickering.



Zotia International Trade Ltd.
201 Rowntree Dairy Road
Woodbridge, ON, L4L 8B8

T: 905-669-1966
F: 905-851-5262

E: info@zotia.ca
W: www.dawnray.ca

